


REPORT

TRUESDAIL LABORATORIES, INC.

CHEMISTS - MICROBIOLOGISTS - ENGINEERS
RESEARCH - DEVELOPMENT - TESTING



14201 FRANKLIN AVENUE
TUSTIN, CALIF. 92680
AREA CODE 714 • 730-6239
AREA CODE 213 • 225-1564
FAX 714 • 730-6462

CLIENT **Douglas Aircraft Company**
Internal Mail Code 74-41
3855 Lakewood Blvd.
Long Beach, CA 90846
SAMPLE Attention: Ron Fornator

DATE August 2, 1991
RECEIVED July 22, 1991
LABORATORY NO. 47634

Water From Stormdrain, Torrance Facility
P.O. #T & M 25998C
INVESTIGATION

**Third Quarter Analysis As Required By
NPDES Permit #CA0001414**

RESULTS

A one gallon grab sample was taken from the stormdrain at 1:05 p.m. on July 19, 1991, by a representative of Truesdail Laboratories, Inc.

pH, Units (150.1) 5.9
Temperature, °F 70

<u>Parameter</u>	<u>Method</u>	MILLIGRAMS PER LITER	
		<u>Detection Limit</u>	<u>Concentration</u>
Suspended Solids	EPA 160.2	4.0	32.0
BOD	EPA 405.1	2.0	310.0
Oil and Grease	EPA 413.1	6.0	ND

Respectfully submitted,
TRUESDAIL LABORATORIES, INC.

Brian C. Puncochar
Brian C. Puncochar, Manager
Environmental Field Services

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.